



OIL CONNECTION POINTS SUMMARY		
(REFER TO MANUAL FOR FURTHER INFORMATION)		
DESCRIPTION	THREAD SIZE	QTY
LUBE QUILL(LQx)	1/4 NPT (F)	1
LUBE POINTS(LPx)	1/4 NPT (F)	8

NOZZLE CONNECTIONS	BOLT HOLE SIZE
N1 8" GAS SUCTION FLANGE (ANSI CLASS 150 FLAT FACE)	8 x 3/4-10 ∇ 1.25
N2 6" GAS DISCHARGE FLANGE (ANSI CLASS 150 FLAT FACE)	8 x 3/4-10 ∇ 1.25
W1A 2 NPT(F) WATER INLET (SEE NOTE 2)	N/A
W1B 2 NPT(F) WATER INLET (SEE NOTE 2)	N/A
W2 2 NPT(F) WATER OUTLET	N/A
D1 1/2 NPT DRAIN HOLE	N/A
D2 1/2 NPT DRAIN HOLE	N/A
D3 1/8 NPT (F) SEAL WEEPAGE DRAIN	N/A

- NOTES:
- CENTER OF MASS DIMENSIONS ARE APPROXIMATE
 - EITHER WATER INLET MAY BE USED, DEPENDING UPON SYSTEM NEEDS
 - WEIGHT IS APPROXIMATE
 - THIS DRAWING IS DUAL DIMENSION. DIMENSIONS WITHOUT BRACKETS ARE IN INCHES, DIMENSIONS IN [BRACKETS] ARE IN MILLIMETERS.
 - REMOVE (3) RED SEAL LOCKING TABS BEFORE OPERATION. RETAIN TABS AND SCREWS FOR SERVICE (TABS MUST BE INSTALLED BEFORE SEAL REMOVAL).